1-700 - 686 6770

425-9171

26

1990 Unregulated Sites

### **Master List**

-250 des

This master list of unregulated sites was compiled by Ohio EPA's Division of Emergency and Remedial Response Section. It is a State version and expansion of U.S. EPA's CERCLIS database developed to ensure investigations of alleged hazardous substance sites. However, Ohio EPA does not warrant this to be the total universe of hazardous substance sites. We anticipate additional site discoveries as our program develops.

### Background

Superfund, the popular name for the Comprehensive Environmental Response, Compensation and Liability Act (CERCLA) of 1980, provides the mechanism to address "abandoned" hazardous waste sites. It constitutes a major milestone in environmental protection and remediation as it not only defines "hazardous substances", but imposes retroactive liability provisions upon the generators, transporters, and others, who often times had disposed of wastes in accordance with all then-existing environmental regulations. It also provides the "Superfund" to remediate the nation's worst sites should the identified responsible parties fail to do so.

Section 103(c) of CERCLA, a one time reporting provision, required every person who owned or operated a facility where hazardous substances had been stored or disposed and which were not permitted under the Resource Conservation and Recovery Act (RCRA) to notity U.S. EPA of the existence of the facility by June 9, 1981. U.S. EPA used this information to create an inventory of potential problem sites. This list evolved into the Emergency Remedial Response Inventory System (ERRIS), which currently is known as CERCLIS, the Comprehensive Environmental Response, Compensation and Liability Information System.

The preliminary assessment (PA) is the first step in the investigative process, described in the Code of Federal Regulations (CFR), Part 300 of the National Comingency Plan (NCP). The NCP outlines the steps which must be taken to respond to sites needing immediate removal or remedial actions. The preliminary assessments Ohio EPA has completed serve to screen sites in need of further investigation to determine if hazaroous substance problems exist.

Most of Ohio's CERCLIS sites have been assessed. A federal grant was received in 1983 to complete PAs. Ohio has continued to complete assessments for the past six years and recently received federal funding for Federal Fiscal Year 1990 for this ongoing process.

Assessments were prepared by staff in Ohio EPA's five district offices to ensure that all file information as well as that known by the office staff could be presented in the assessments. The documents were routed through the central office for quality assurance and administrative purposes prior to being forwarded to U.S. EPA and identified owners or operators. The PAs are considered public information.

Ohio EPA determined that sites posing any threat to the environment or populations would be a State profity for additional investigations. If available information indicated hazardous conditions were potentially affecting people, Ohio EPA considered the site to be "medium" priority; those with known hazardous conditions were prioritized "high". The "low" priority sites have little evidence to indicate a problem exists and "zero" priority sites have been found not to be a hazardous substance problem. A blank space indicates the PA has not been completed.

Ohio EPA assigned a secondary priority rating to most of the listed sites. This rating is used to ask U.S. EPA to assign a contracted Field Investigation Team (FIT) to perform follow-up site inspections. The FIT priority ratings include: high, medium, low, no further action, and "Yes" for site inspection. Ohio EPA assigns each site to one of these categories based on the site's likelihood to score near or above the National Priority List cutoff point. U.S. EPA considers Ohio EPA's FIT priority request, but ultimately proritizes additional activities at its discretion. THESE PRIORITIES REFLECT THE POTENTIAL FOR HAZARDOUS SUBSTANCE RE-LEASE TO THE ENVIRONMENT AS INITIALLY EVALUATED.

The investigative process continues after the PA as warranted, following the NCP. The subsequent step is a Site Inspection (SI), which should include generation or analytical information. The SI-generated analytical information combined with a more thorough understanding of populations potentially at

LP.	1/
DT	
MAB	<u></u>

risk provides a means to further screen and prioritize additional investigations. The comprehensive problem evaluation and remedy selection is completed by way of a remedial investigation/leasibility study (RV FS).


In many instances Ohio EPA, U.S. EPA or potentially responsible parties have generated additional information to more fully characterize these sites. In some instances, site conditions have been improved through the initiative of the owners or other identified responsible parties. This list does not report such interim activities.

U.S. EPA will provide funding or manpower only for further investigations at sites with the potential to score near or above the Hazard Ranking System (HRS) cutoff. The current HRS, which is described in

40 CFR, Part 300, will be revised soon. Federal funding is expected to address only a portion of Chio sites. Chio EPA recently released a funding study which estimates it will cost up to six billion dollars to clean up hazardous waste sites in Chio which do not warrant federal funds.

This list includes approximately 1100 actual sites. Several sites have multiple aliases. The list includes the U.S. EPA and Ohio EPA identification numbers; site name and address; the Federal or FIT priority; the State priority; and if the site is on CERCLIS or a duplicate listing. (Several abbreviations noted: SIA – Surface Impoundment Assessment; AKA – Also Known As; ILA – Initially Listed As).

Ohio EPA's Division of Emergency and Remedial Response will provide annual updates of this list.



For Additional Information, contact the Ohio EPA District Office, Division of Emergency and Remedial Response, In your area. Northeast: 216-425-9171; Northwest: 419-352-8461; Southeast: 514-385-8501; Southwest: 513-285-6357; Cantral: 614-771-7505

Page No. 12/08/89 93

U.S. EPA ID OHIO EPA ID	SITE NAME AND ADDRESS		PRIORITY FIT .
OHD980612212 374-0710 ON CERLCIS	SAN-LAN CORP CO RD 18 & POPLAR ST FOSTORIA	44830	PRIORITY = M FIT = M
OHD980611826 374-0724 ON CERLCIS	SENECA CHIEF INC 403 HOWARD FINLEY	45404	PRIORITY = L FIT = L
NOT ASSIGNED 374-1036 NOT ON CERCLIS	SENECA WIRE 319 S VINE ST FOSTORIA	44830	PRIORITY = FIT =
CHD980611826 374-0757 ON CERLCIS	SPERRY REMINGTON 210 WALL ST TIFFIN	44883	PRIORITY = L FIT = L
CHD980611529 374-0807 CN CERLCIS	TIFFIN LANDFILL SW CO RD 38 43 REPUBLIC	44867	PRIORITY = L FIT = L
** COUNTY = SHEI			
	CENTRAL OIL ASPHALT CORP CAMPBELL & VANDEMARD STS SIDNEY		PRIORITY = L FIT = L
OHD000605451 575-0727 ON CERLCIS	SHELBY CO SAN LDFL ST RTE 47 1 MI E OF SIDNE SIDNEY	EY 45365	PRIORITY = H FIT = H
+- COMMITT			
** COUNTY = STAP CHD980704522 276-0930 CN CERLCIS	#64 PENNOCK RD JUNK YARD 617 PENNOCK RD MASSILLON	44646	PRIORITY = L FIT = L
OHD004173027 276-0011 ON CERLCIS	ACME HARD CHROME INC 540 N FREEDON ST ALLIANCE	44601	PRIORITY = 0 FIT = 0

U.S. EPA ID OHIO EPA ID	SITE NAME AND ADDRESS		PRIORITY FIT
OHD981189343 276-0012 ON CERLCIS	ACME LDFL CORNER HARMON PL & ROYAL CANTON		PRIORITY = M FIT = M
OHD981090418 276-0038 ON CERLCIS		44601	PRIORITY = L FIT = L
OHD048107049 276-0065 ON CERLCIS	ASHLAND PETROLEUM CO CAN'S 2408 GAMBRINUS RD CANTON	TON REF	PRIORITY = M FIT = M
OHD092626621 276-0078 ON CERLCIS	BABCOCK & WILCOX CO RESER 1562 BEESON ST	ARCH & DEV DIV	PRIORITY = M FIT = L
OHD980704449 276-0082 ON CERLCIS		44711	PRIORITY = M FIT = M DUPLICATE
NOT ASSIGNED 276-1117 NOT ON CERCLIS	BEACH CITY LANDFILL	44608	PRIORITY = FIT =
OHD980610109 276-0088 ON CERLCIS	BELDEN AVE #1 SCA SERVICE 3020 BELDEN AVE	ES INC 44707	PRIORITY = L FIT = L
OHD980509624 276-0108 ON CERLCIS	BREITENSTINE LDFL CHAPEL ST 1/4 MI W OF ST WAYNESBURG	RTE 44 44688	PRIORITY = L FIT = L
OHD004465142 276-0130 ON CERLCIS	· ·	44706	PRIORITY = L FIT = L
OHD004461554 276-0131 ON CERLCIS	CANTON METAL ALLOY CO 1551 BELDON AVE SE CANTON	44707	PRIORITY = M FIT = M

			•
U.S. EPA ID OHIO EPA ID	SITE NAME AND ADDRESS		PRIORITY FIT .
OHD004462255 276-0133 ON CERLCIS	CANTON WOOD PRODS 220 TUSCARAWAS ST E CANTON	44702	PRIORITY = H FIT = H
OHD980704787 276-0132 ON CERLCIS	CANTON WORKS (DU PONT) ALLEN & 17TH STREETS CANTON	44708	PRIORITY = L FIT = L
OHD980704282 276-0176 ON CERLCIS	CITY SALT STORAGE SITE 9TH & SHROYER ST CANTON	44711	PRIORITY = 0 FIT = 0
	CONTRACTORS PANELING WARE 3704 LINCOLN ST E CANTON	HOUSE	PRIORITY = M FIT = L
CHD004460457 276-0255 ON CERLCIS		44601	PRIORITY = L FIT = L
	D-CON/WAREHOUSE FIRE 1250 ASBESTOS DRIVE ALLIANCE	44641	PRIORITY = FIT =
OHD004468609 276-0231 ON CERLCIS	DICE DECAL CORP 7390 MIDDLEBRANCH RD MIDDLEBRANCH	44652	PRIORITY = L FIT = L
OHD004217972 276-0261 ON CERLCIS	EATON CORP 240 4TH ST NW	44646	PRIORITY = L FIT = L
	EKCO HOUSEWARES 359 STATE AVENUE N.W./PO	BOX 560 44648	PRIORITY = FIT =
OHD980568992 276-1135 ON CERLCIS	ENVIRITE CORP. CANTON INDUSTRIAL PLT. CANTON	44707	PRIORITY = 0 FIT = 0

96

Ohio EPA
Remedial Response Section
Unregulated Sites Master List
Alpha by County

M - Macan H - Ibigu O - Zaro

1 Find on the second

U.S. EPA ID OHIO EPA ID	SITE NAME AND ADDRESS	•	PRIORITY
276-1121	GREENTOWN DUMP/MILLER LAN 2365 STATE STREET NW	NDFILL	PRIORITY = FIT =
NOT ON CERCLIS	GREENTOWN	44630	
OHD004462131 276-0405 ON CERLCIS	HOOVER CO PLT 1 101 E MAPLE ST NORTH CANTON	44720	PRIORITY = M FIT = M
OHD980614036 276-0406 ON CERLCIS	HOOVER CO THE S SIDE OF STRATAVON DR NORTH CANTON	44720	PRIORITY = M FIT = M
OHD000377911 276-0416 ON CERLCIS	INDUSTRIAL EXCESS LDFL 4 MI S I-619 & CLEVELAND UNIONTOWN	AVE 44685	PRIORITY = H FIT =
OHD004205464 276-0433 ON CERLCIS	JONES & LAUGHLIN STEEL CO 1500 W MAIN ST LOUISVILLE	ORP LOUISVILLE	PRIORITY = L FIT = 0
NOT ASSIGNED 276-1119	KIM TAM	44605	PRIORITY = FIT =
NOT ON CERCLIS	ONTONTOWN	44685	
OHD980704357 276-0444 ON CERLCIS	KLAMER BARREL 415 4TH ST NW CANTON	44702	PRIORITY = 0 FIT = 0
NOT ASSIGNED 276-1120 NOT ON CERCLIS	LAKEMORE DUMP MAIN STREET	44250	PRIORITY = FIT =
NOT ASSIGNED 276-1116 NOT ON CERCLIS		44707	PRIORITY = FIT =
OHD980422919 276-0468 ON CERLCIS	LIQUID CARBONIC CORP 5200 LOUISVILLE ST NE CANTON	44705	PRIORITY = M FIT = M

Page No. 97 12/08/89

U.S. EPA ID OHIO EPA ID	SITE NAME AND ADDRESS		PRIORITY FIT
OHD004469094 276-0500 ON CERLCIS	MASSILLON STEEL CASTING 577 OBERLIN RD SW MASSILLON	CO (SIA) 44646	PRIORITY = L FIT = L
0HD986967610 276-1069 ON CERLCIS	MERRIT PLASTICS INTERSECTION OF COLUMBUS NORTH CANTON	S& HARMONT 44720	PRIORITY = FIT =
OHD980683221 276-0985 NOT ON CERCLIS	MILLERTON RD BARRELL DUM MILLERTON RD BTWN WARREN		PRIORITY = M FIT = M
OHD048416697 276-0535 ON CERLCIS	MOE PAUL G AKA VISTAR IN 7291 SWAMP RD HARTVILLE	44632	PRIORITY = L FIT = 0
CHD980423099 276-0542 CN CERLCIS	MORGAN ENGINEERING CO (S 947 E BROADWAY ALLIANCE	IA) 44601	PRIORITY = M FIT = M
OHD980610091 276-0546 ON CERLCIS	MPS INC 4124 SOUTHWAY ST SW CANTON	44706	PRIORITY = M FIT = M
CHD004253477 275-0602 ON CERLCIS	OHIO TRANSFORMER CORP 1776 CONSTITUTION AVE LOUISVILLE	44641	PRIORITY = L FIT = 0
OHD051630051 276-0986 ON CERLCIS	PETROLEUM & POWER MAINTE 309 NORTH ST LOUISVILLE	NANCE	PRIORITY = FIT =
OHD004228003 276-0677 ON CERLCIS	REPUBLIC STEEL CENTRAL A 2633 8TH ST NE CANTON	LLOY CANTON 44701	PRIORITY = H FIT = 0
OHD004227948 276-0669 ON CERLCIS	REPUBLIC STEEL DRAINAGE 4416 LOUISVILLE RD NE CANTON	PROD FAIRHOPE	PRIORITY = M FIT = M

U.S. EPA ID OHIO EPA ID	SITE NAME AND ADDRESS		PRIORITY FIT
OHD990834129 276-0670 ON CERLCIS	REPUBLIC STEEL ENDURO DIV 410 OBERLIN RD SW MASSILLON	44646	PRIORITY = M FIT = L
OHD004218095 276-0672 ON CERLCIS		ND PROD DIV	PRIORITY = L FIT = L
	REPUBLIC STEEL-SO WORKS 2149 HARRISON AVE SW CANTON		
OHD097952642 276-0715 ON CERLCIS	SCA SERV OF OHIO INC DUES 4720 DUEBER AVE SW	3ER RD 44706	PRIORITY = M FIT = L
		44652	PRIORITY = L FIT = L
	ST REGIS PAPER CO 2820 WINFIELD WAY NE	44705	PRIORITY = L FIT = L
OHD980281612 276-0809 ON CERLCIS	TIMKEN CO GAMBRINUS BEAR DUEBER & GAMBRINUS AVES CANTON	ING & STEEL (SIA)	PRIORITY = M FIT = M
OHD004465100 276-0810 ON CERLCIS			PRIORITY = M FIT = M
OHD004179339 276-0827 ON CERLCIS		44657	PRIORITY = H FIT = L
OHD048341002 276-0837 ON CERLCIS	UNION METAL MFG CO (SIA) 1432 MAPLE AVE NE CANTON	44705	PRIORITY = L FIT = L

U.S. EPA ID OHIO EPA ID	SITE NAME AND ADDRESS		PRIORITY FIT
OHD000821504 276-0847 ON CERLCIS	UNIVERSAL COOPERATIVES I 510 W ELY ST ALLIANCE	NC 44601	PRIORITY = M FIT = M
OHD980704688 276-0853 ON CERLCIS	UNNAMED DRAINAGE DITCH 1500 BLOCK OF WAYNESBURG CANTON	44707	PRIORITY = L FIT = L
OHD980704696 261-0860 ON CERLCIS	US CERAMIC TILE CO 10233 SANDYVILLE RD CANTON	44711	PRIORITY = L FIT = 0
0HD986967602 276-1070 ON CERLCIS	VACANT LOT INTERSECTION OF MIDDLEBR NORTH CANTON	ANCH&MARTIN 44720	PRIORITY = FIT =
OHD051522324 276-0905 ON CERLCIS	WHITE ENGINE INC 101 11TH ST SE CANTON	44707	PRIORITY = L FIT = 0
* COUNTY = SUM OHD000716910 277-0002 ON CERLCIS	MIT 3M COPLEY CHEM 3154 COPLEY RD COPLEY	44321	PRIORITY = M FIT = M
OHD089887996 277-0987 ON CERLCIS	ABC DEMOLITION CO INC 359 HARRIS ST AKRON	44304	PRIORITY = M FIT = L
OHD050387802 277-0017 ON CERLCIS	AEROSOL SYSTEMS INC 9150 VALLEY VIEW RD MACEDONIA	44056	PRIORITY = L FIT = L
OHD000605410 277-0020 ON CERLCIS	AKRON CITY LDFL 1505 HARDY RD AKRON	44313	PRIORITY = M FIT = L
OHD980680003 277-0021 ON CERLCIS	AKRON LDFL & WASTE HAZEL ST AKRON	44305	PRIORITY = M FIT = M